

Title: A18 The wind turbine blades fell off

Generated on: 2026-04-30 10:14:50

Copyright (C) 2026 ESAFETY SOLAR CONTAINER. All rights reserved.

-----

Stunning video from Buzzards Bay in Plymouth shows a broken wind turbine after one of the blades became detached on Friday afternoon. The blade fell into a cranberry bog below the turbine.

All three blades have fallen off a single wind turbine located on the grounds of British insurance company Aviva in Perth, Scotland.

Operations at the 130MW Sormarkfjellet wind farm in Norway have been halted after a turbine blade partially fell to the ground, energy company Aneo confirmed. The wind farm, located in ...

After part of a blade on one of the Vineyard Wind 1 offshore turbines broke off and fell into the ocean over the weekend, the company put two teams to work on Tuesday to seek out and...

COPENHAGEN, April 11 (Reuters) - A 72-metre (236 ft) long blade fell off a wind turbine in Norway late on Wednesday, the Odal Vind wind farm said, adding that no one had been hurt in the incident.

The collapse of the 71-metre-long (232 ft) wind turbine blade comes at a time when nearly half of the machines at the site are not working amid an ongoing process conducted by turbine maker ...

NANTUCKET, Mass. (AP) -- The maker of a massive wind turbine blade that broke apart off Nantucket Island and washed up on the beaches says a manufacturing problem was responsible.

COPENHAGEN, April 11 (Reuters) - A Siemens Gamesa wind turbine blade weighing 22 metric tons fell off the machinery on Wednesday but no one was hurt, the Odal Vind wind farm in Norway...

Website: <https://esafet.co.za>

